



**Project:**

Atlantic Holding Tank Rehabilitation

**System:**

Nukote ST

**Description:**

The project entailed waterproofing a leaking effluent tank in the paper industry. The client needed a waterproofing solution to be applied on the tank exterior because it could not be taken out of service. ICC applied Nukote primers that would bond to the tank exterior. Then, on top of the primers, ICC sprayed Nukote ST to ensure the tank was watertight.

**Client:**  
Atlantic Packaging Ltd.

**Manufacturer:**  
Nukote Coating  
Systems

**Contractor/Distributor:**  
Infrastructure Coatings  
Corp.

**Area:**  
1200 m<sup>2</sup>

**Location:**  
Ontario, Canada

**Date:**  
2018