

**Project:**

Lining for Recovered Bitumen Tank Overflow Sump  
Primary & Secondary Containment Area

**Date:**

May 2015

**Description:**

The client's Consultant specified a Membrane on concrete that was resistant to chemicals, yet flexible enough to move with concrete even in extreme cold conditions.

All new concrete was abrasive blasted and Nukote HLT applied to seal concrete. A 100% solids epoxy patching compound was used for bug holes. Fast set Nukote PolyPrime II was applied as primer to facilitate quick turnaround at low temperatures. Nukote ST Polyurea was immediately applied at a minimum thickness of 2 mm.

**Client:**  
Major Oil Company -  
Alberta

**Distributor:**  
Nukote Coating Systems  
Canada Inc.

**Contractor:**  
Kiewit

**Applicator:**  
Stray Cat Industrial

**System:**  
Nukote HLT  
PolyPrime II  
Nukote ST

